

STANDARD PACKAGE

1. Carrying bag
2. Power meter
3. Kevlar scissors, new style
4. F.O. visual fault locator
5. Manual pro cleaver
6. FTTH drop fiber stripper, new style
7. 3 hole fiber stripper, new style
8. F.O. Stripper and length bar
9. F.O. clean stick 2.5 mm.
10. Alcohol's bottles



Part Number	Description
UFH3020	FTTH PROFESSIONAL TOOL w/Power meter

FIBER OPTIC TOOL KIT

KIT CONTENTS

1. UF-2821 WIPE PAPER
2. UF-2823 CLEANSER LIQUID
3. UF-2826 A/B FAST EPOXY GLUE (COMPLETE BOND 30 MINUTES)
4. UF-2825 EPOXY SYRINGE
5. UF-2830 (0.3mm - WHITE COLOR) POLISH FILM
6. UF-2831 (1.0mm - GREEN COLOR) POLISH FILM
7. UF-2835 (5.0mm - BROWN COLOR) POLISH FILM
8. UF-2803 FIBER COATING 250-900mm STRIPPER
9. UF-2804 KEVLAR SCISSORS
10. UF-2806 CRIMP TOOL (ST, SC, FC)
11. UF-2808 CARBIDE SCRIBE
12. UF-2810 ST POLISH DISC
13. UF-2812 SC POLISH DISC
14. UF-2814 RUBBER WORKING PAD
15. UF-2816 GLASSES WORKING PAD
16. UF-2825 SYRINGE
17. EPOXY MIXER
18. EPOXY MIXER PAD



Part Number	Description	Box Dimension L x W x H(mm)
UF-2840	Fiber Optic PROFESSIONAL TERMINATE SET (No Optical Scope)	297 x 197 x 60

CLEAVER AUTO / MANUAL, F.O. MICROSCOPE, F.O. VISUAL FAULT LOCATOR



UF-2844A



UF-2851



UF-2883

Part Number	Description	Battery
UF-2844	F.O. Auto Pro Cleaver	-
UF-2845	F.O. Manual Pro Cleaver	-
UF-2851	F.O. Microscope 400X w/ST, SC, FC & LC Adapter	2A x 3
UF-2883	F.O. Visual Fault Locator (Heavy Duty) > 10 mw for ST, SC, FC (7 Km.)	2A x 2
UF-2884	F.O. Visual Fault Locator (Heavy Duty) > 10 mw for LC (7 Km.)	2A x 2
UF-2885	F.O. Identifier	2A x 2